دستگاه دوزیمتری و کنترل کیفی رادیولوژی

CHARGING CONTACT
MODEL 909
DOSIMETER CHARGER
PUSH ROD
TO ZERO
ZEROING KNOB
CAUTION: Do not press PUSH ROD when charging. Dosimeter may be damaged.
TO READ: Place Dosimeter lightly on CHARGING CONTACT (do not press down) and press PUSH ROD to illuminate scale.
TO ZERO: Place Dosimeter on CHARGING CONTACT, Press down until Dosimeter barrel contacts black collar of charging contact and adjust hairline TO ZERO.
Arrow-Tech
417 Main Avenue West
Rolla, North Dakota 58367
Phone: 877-477-6461
Fax: 701-477-6464
Web: www.dosimeter.com
ARROW-TECH, INC.
Model W138-S

RADIATION ALERT®
Digilert 100
mR/hr μSv/hr
CPM CPS
Total/Timer
Audio
On
Off
دانشگاه علوم پزشکی تبریز
دانشکدهٔ پیراپزشکی
طبقه ۵ شماره ۸۸۰

Product USB
Piranha
Chamber Adapter
dell.com/support

FOOT

OHM'S LAW APPARATUS
RHEOSTAT
BATTERY
POWER
OFF
ON
RESISTANCE

TRANSFORMER
6V AC
DIGITAL MULTIMETER
DIGITAL MULTIMETER

آزمایش بررسی قانون ارشمیدس

MEDISON
Tena
ULTRA